

Date: 7th August 2013

R315X - BRINK STRETCH JACKET



Measures in Cms

TO FIT APPROX CHEST SIZE	SIZE	S	M	L	XL	XXL	3XL	TOL +/-
	UK (INCHES)	38	40	42	44	46	48	
	EURO (CMS)	48	50	52	56	58	60	
A	1/2 CHEST MEASURE 2CM BELOW UNDERARM - LAY JACKET OUT FLAT	54	56	58	60	62	64	1
B	BACK LENGTH	66	68	70	72	74	76	1
C	OVERARM SLEEVE LENGTH FROM SHOULDER SEAM	64	65	66	67	68	69	1

